


DAF F.A.P

Marque	Réf. Origine	Réf. HOBI NEUF	Réf. HOBI RECONDITIONNE	Moteur
DAF CF - XF	1945456	3B0001	3B0001R	MX-11 210/240/271/291/320 MX-13 303/340/375 EURO 6
	1945456R			
	1891485			
	2137441			
DAF CF - LF	1961522	7BJ996	7BJ996R	PX-7 164/186/208/231 EURO 6
	1961522R			
DAF LF	1997433	51711	51711R	PX - 5 112/135/157 EURO 6
	1997433R			
	2137442			
	2137442R			

Chez DAF "R" après la référence = Echange Standard

		
3B0001	7BJ996	51711

DAF KITS COLLIERS + JOINTS

	Réf. HOBI KIT	Réf. Origine	Remarques
	7BJ992	1927181	Pour 3B0001
	7BM977	1976845	Pour 7BJ996 Collier seul : 1997443 joint seul: 1827320
	7BM980	1997442	Pour 51711 Collier seul : 1997443 joint seul: 1827320


SCANIA F.A.P

Marque	Réf. Origine	Réf. HOBI NEUF	Réf. HOBI RECONDITIONNE	Moteur
SCANIA P / G / R	570759 (ES)	2B0001	2B0001R	DC09 108/111/112/113 DC13 115/116/124/125 EURO 6
	2269640(PN)			
	570757			
	2097594			
SCANIA P / G / R	570749(ES)	4MJ998	4MJ998R	DC16 101/102/103 EURO 6
	2446964(PN)			
	570758			
	2222655			

(ES) = Echange Standard (PN) = Pièce Neuve

		
2B0001	6LI001	

SCANIA JOINTS

	Réf. HOBI JOI	Réf. Origine	Remarques	
	4MM995	2588429	2168586	Pour 2B0001
	4MM990	2431439	2217917	Pour 4MJ998

RENAULT - VOLVO F.A.P

Marque	Réf. Origine	Réf. HOBI NEUF	Réf. HOBI RECONDITIONNE	Moteur
RENAULT VOLVO	7485013517(ES)	1B0001	1B0001R	D5K 210/240 D8K 250/280/320 EURO 6
	7421922964(PN)			
	85013698(ES)			
	21922979(PN)			
	21794709			
RENAULT VOLVO	21922964	1B0002	1B0002R	D11K 330/370/410/450 D13K 420 EURO 6
	21750157			
	7485013301(ES)			
	7421775800(PN)			
	85013300(ES)			
RENAULT VOLVO	21775798(PN)	1B0003	1B0003R	D13K 460/500/540 D16K 550/650/750 EURO 6
	21716414			
	21716416			
	21775800			
	7485013298(ES)			
RENAULT VOLVO	7421775802(PN)	1B0003	1B0003R	D13K 460/500/540 D16K 550/650/750 EURO 6
	85013297(ES)			
	21775801(PN)			
	21716417			
	21716419			
	21775802			

(ES) = Echange Standard (PN) = Pièce Neuve



1B0001



1B0002



1B0003

RENAULT - VOLVO KITS COLLIERS + JOINTS



Réf. HOBI	Réf. Origine
1G0005	Pour 1B0001 Grand Collier = 21664904 Petit Collier = 21664906 Joint....(2x) = 21664918
	Pour 1B0002 et 1B0003 Grand Collier = 21445539 Petit Collier = 21445536 Joint....(2x) = 21570880
1G0006	

MAN F.A.P

Marque	Réf. Origine	Réf. HOBI NEUF	Réf. HOBI RECONDITIONNE	Moteur
MAN TGL	81151039123(ES)	5B0002	5B0002R	D0834LFL 66-68 / 75-76/77 EURO 6
	81151030123(PN)			
	81151039113			
	81151030113			
MAN TGM	81151039124(ES)	5B0003	5B0003R	D0836LFL 66-68 / 75-77 EURO 6
	81151030124(PN)			
	81151039111			
	81151030111			
MAN TGS - TGX	81151039107(ES)	5B0001	5B0001R	D2066LF61/67/68/76/78 D2676LF 25/26/35/36 D3876LF01/02/04/05
	81151030107(PN)			
	81151039130			
	81151036130			

(ES) = Echange Standard (PN) = Pièce Neuve



MAN COLLIERS et JOINTS

	Réf. HOBI	Réf. Origine	Remarques
	Pour 5B0002		
	2JM978	06674314282	Collier grand 40x14x282
	2JM980	06674314125	Collier petit 40x14x125
	2JM973	81159010045	joint D 279
	2JM982	81159010046	joint D 122
Pour 5B0003			
	2JM984	06674314307	Collier grand 40x14x307
	2JM980	06644314125	Collier petit 40x14x125
	2JM986	81159010047	joint D 304
	2JM973	81159010045	joint D 279
	2JM982	81159010046	joint D 122
Pour 5B0001			
	2JM992	81974200184	Collier grand 25x378
	2JM994	81974200185	Collier petit 25x221
	2JM996	81159010043	joint grand
	2JM993	81159010044	joint petit

MERCEDES F.A.P

Marque	Réf. Origine	Réf. HOBI NEUF	Réf. HOBI RECONDITIONNE	Moteur
--------	--------------	-------------------	----------------------------	--------